



Арт. №	Описание	Длина мм	Упаковка (шт.)
4001005	PZ1	25	1
4001055	PZ1	50	1
4001105	PZ1	70	1
4001006	PZ2	25	1
4001056	PZ2	50	1
4001106	PZ2	70	1
4001007	PZ3	25	1
4001057	PZ3	50	1
4001107	PZ3	70	1
4001008	PZ4	25	1
4001058	PZ4	50	1

## BIT Насадка Позидрайв



Арт. №	Описание	Длина мм	Упаковка (шт.)
4001001	RH1	25	1
4001051	RH1	50	1
4001101	RH1	70	1
4001002	RH2	25	1
4001052	RH2	50	1
4001102	RH2	70	1
4001003	RH3	25	1
4001053	RH3	50	1
4001103	RH3	70	1
4001004	RH4	25	1
4001054	RH4	50	1

## BIT Насадка Филлипс



Арт. №	Описание	Длина мм	Упаковка (шт.)
4001032	T10	25	1
4001042	T10	50	1
4001132	T10	70	1
4001033	T15	25	1
4001043	T15	50	1
4001133	T15	70	1
4001034	T20	25	1
4001044	T20	50	1
4001134	T20	70	1
4001035	T25	25	1
4001045	T25	50	1
4001135	T25	70	1
4001036	T27	25	1
4001046	T27	50	1
4001136	T27	70	1
4001037	T30	25	1
4001047	T30	50	1
4001137	T30	70	1
4001038	T40	25	1
4001048	T40	50	1
4001138	T40	70	1

## BIT Насадка Торкс



Арт. №	Описание	Длина мм	Упаковка (шт.)
4001059	0.5x3.0	50	1
4001009	0.6x3.5	25	1
4001060	0.6x3.5	50	1
4001010	0.8x4.0	25	1
4001061	0.8x4.0	50	1
4001062	1.0x5.5	50	1
4001011	1.2x6.5	25	1
4001063	1.2x6.5	50	1
4001012	1.6x8.0	25	1
4001064	1.6x8.0	50	1

## BIT Насадка Шлиц



Арт. №	Описание	Упаковка (шт.)
4001013	Адаптер 1/4" / 1/4"	1

## MMH Магнитный держатель



Арт. №	Описание	Упаковка (шт.)
4001016	Адаптер SDS-Plus / 1/4"	1

## MMH Магнитный держатель

